

- - 4. SOME MINOR ROUTE DEVIATIONS DUE TO UNDERCAST.
 - 5. IMC FAILURE WILL BE COVERED THOROUGHLY IN TECHNICAL REPORT.
 NO APPRECIABLE EFFECT ON MISSION RESULTS SINCE AREA MISSED CLOUD

 COVERED.
 - 25X1A 6. OVERLAY THIS MISSION BEST EXAMPLE YET OF EXCESSIVE AND

 UNNECESSARY DATA. STILL SEEMS UNREASONABLE TO TO LIST ANY
 REPEAT ANY COORDINATES ON OVERLAY EXCEPT MATCHING COORDINATES.

 FURTHER, ONCE COORDINATES DEFINING ALFA PARTICULAR POINT ARE LISTED

 IN YOUR HBJ DASH ONE ZERO ZERO ALL REFERENCE TO THAT POINT IN

 FUTURE HBJ MESSAGES SHOULD BE ONLY BY LETTER DESIGNATION WITH NO NEED

 REPEAT COORDINATES. SOME REPORTS REQUIRE REPETITION. EFFECTIVE

 NOW NEEDLESS REPETITION COORDINATES IN HBJ MESSAGES WILL BE

25X1A

25X1A

7. DASH ONE PERFORMANCE EXCELLENT.

OPERATIONAL IMMEDIATE

25X1A

OFF1R0002001000F4-3